

Making progress possible. Together.

REPORT TO SUB-COUNCIL 16:

1. ITEM NUMBER:

16 SUB 46/10/19

2. SUBJECT

RESPONSE FROM TRANSPORT DEPARTMENT TO REQUEST FOR TRAFFIC CALMING MEASURES: KLOOF ROAD, SEA POINT

3. PURPOSE

To consider the recommendations from the Transport Department as to a request for traffic calming measures at Kloof Road, Sea Point.

4. STRATEGIC INTENT

Safety and Security

5. FOR DECISION BY

Delegation: Part 24 9(1) To decide within its area of jurisdiction where traffic calming measures are to be applied within the relevant legislation and policy and after considering a report from the Transport and Urban Development Authority.

6. EXECUTIVE SUMMARY

An application for implementing traffic calming measures at Kloof Road Sea Point, was referred to the Transport Department for a technical assessment and report to Subcouncil 16 in terms of Council's Traffic Calming policy.

The attached letter dated 19 September 2019 to the Subcouncil (Annexure A) reflects the recommendations of the Director: Transport.

7. RECOMMENDATION

Having considered the City of Cape Town Traffic Calming Policy, Transport Department therefor indicates that;

After evaluating the request, to increase visibility and attention to signage:

TO BE LEST STATE AND A TO STATE AND	Making progress possible. Together
	waking progress possible. logether

- a) We recommend replacing the existing signage with a bigger size and different signage class and to relocate the one sign, as per the attached proposed design.
- b) We do not advise the implementation of the flashing lights, due to possible vandalism and maintenance issues.

8 DISCUSSION/CONTENTS

The Ward Councillor, N Jowell, Ward 54, received a request for traffic calming measures. The application was dealt with in terms of Council's Traffic Calming Policy.

8.1 Constitutional and Policy Implications

In terms of Council's traffic calming policy, the Transport and Urban Development Authority will assess the application and make a recommendation to the Subcouncil for decision.

8.2 **Environmental implications**

Does your report have any environmental implications:	No 🛚	Yes 🗌
Staff implications		
Does your report impact on staff	No 🗵	Yes 🗌

8.4 Other Services Consulted

being required?

resources or result in any additional staffing resources

Transport and Urban Development Authority - Deon Manuel

uzanan manan manan manan mazarah Persah Persah	Making	progress	possible.	Together.

8.3

ANNEXURES:

A: Memo from Transport Urban Development Authority dated 19 September 2019

B. Proposed design of 40 Kloof Road.

FOR FURTHER DETAILS CONTACT:

NAME	Vivienne Sasman
CONTACT NUMBERS	021 487 2055
E-MAIL ADDRESS	Vivienne.Sasman@capetown.gov.za
DIRECTORATE	Urban Management
FILE REF NO	

Lucille	Mu	ller (Acting)	
Manage	∍r:	Sub	council	16

Ashell

Date /5/10/19





Making progress possible. Tegether.

Network Management Department

Network Facilitation & Development

T+27 21 444 7131 F+27 86 588 8337 M+27 73 385 7771 E Thulani.Makibi@capetown.gov.za

Internal Memorandum

To : Subcouncil 16

From: Thulani Makibi

Traffic Engineering Technician

Subject: Lines & Signs Request: Kloof Road, Sea Point

Date: 19 September 2019

APPLICATION FOR SIGNAGE, FLASHING LIGHTS AND INCREASED ROAD MARKINGS IN KLOOF ROAD, SEA POINT

1. Introduction

As per the request, Subcouncil 16 believes that:

- Additional road warning signs are essential to notify drivers of a school ahead
- Increased warning needs to be given of the pedestrian crossing ahead to give drivers adequate time to decrease their speed

Subcouncil 16 requests that in order to resolve the matter:

- School ahead signage be installed outside of the school on both lane directions
- Flashing orange lights should be added to the pedestrian crossing poles
- Increased road markings should be painted on the road to warn of the school and pedestrian crossing ahead.

2. Evaluation of Request

Based on the evaluation the following points are noted:

- 1. There are existing road signage and road markings along Kloof Road in the vicinity of the Weizman School.
- 2. The existing W301 sign in Kloof Road (northbound direction) is rotated and does not face traffic (refer to figure 1 below).



Figure 1: Existing W301 sign rotated out of view of traffic along Kloof Road

3. Existing signage (W301 and W308) are fairly close to each other, creating a sense that drivers attention is not drawn quickly enough to notice both signs in place (refer to figure 2 below).




Figure 2: Short distance space between signage as well as existing "school" road marking

3. Conclusion

After evaluating the request, to increase visibility and attention to signage we recommend replacing the existing signage with a bigger size and different signage class, and to relocate the one sign as per the proposed design (INDC2000 HHO-7298-202-2122 Rev 00). We do not advise the implementation of the flashing lights due to possible vandalism and maintenance issues.

Yours faithfully

Thulani Makibi

Principal Traffic Engineering Technician

