

1. ITEM NUMBER: 24SUB 39/08/2021

2. SUBJECT

REMEDIAL ENGINEERING MEASURES WARD 15 - IRENE ROAD

ISIHLOKO

AMANYATHELO OLUNGISO EZOBUNJINELI KWIWADI 15 - eIRENE INDLELA

ONDERWERP

REMEDIERENDE INGENIEURSMAATREËLS VIR WYK 15 – IRENEWEG

3. PURPOSE

To requests that corrective traffic measures be in place at Irene Road, at the bend of where Harwood Road joins Irene Road, Helderberg Estate/Helena Heights, Somerset West.

4. FOR DECISION BY

Decision by Council

Delegation 9.1 to decide within its area of jurisdiction where traffic-calming measures are to be applied subject to the relevant legislation and policy either considering a report from the Transport Department.

5. EXECUTIVE SUMMARY

Irene Road is a class 3 road, which is used by public transport, high volume of traffic and pedestrians and cyclist, is on the road and vehicles speed at unacceptable levels. This complaint came from the resident living on the bend. Drivers speed down the hill and into this left and right hand bend. Need "slow down" signs and sign bend to left /right as well as up?

Sub-council 24 has sent the request to the Transport Department, which will undertake a technical assessment. The Transport Department will interact with the Ward Councillor where necessary and provide written comment on the progress to the Sub-Council Manager.

Attached herewith request forms, illustrating a description of the problem. See Annexure E.

6. RECOMMENDATIONS

- a) That the Sub-council supports and recommends the proposed request for remedial measures at Irene Road, Helderberg Estate/Helena Heights, Somerset West.
- b) That the request be forwarded to the Transport Department for their action and be placed on the Matters Receiving Attention for monitoring.

ISINDULULO

- a) Ukuba iBhungana lisixhasa kwaye lisincome isicelo esicetywayo samanyathelo okulungisa kumdibaniso weIrene Indlela, eHelderberg Estate/eHelena Heights, eSomerset West.
- b) Ukuba isicelo sidluliselwe kwiCandelo lezoThutho ngentshukumo yazo kwaye sibekwe kwiMicimbi yokuFumana ukuBekwa kweliso ukuze ihlolwe.

AANBEVELING

- a) Dat die Subraad steun verleen aan die voorgestelde versoek en aanbeveel vir remediërende maatreëls op Ireneweg, Helderberglandgoed/Helenahoogte, Somerset Wes.
- b) Dat die versoek aan die departement van vervoer gestuur word vir hul optrede en geplaas word op die sake wat aandag geniet vir monitering.

7. DISCUSSION/CONTENTS

See Executive Summary

7.1 Constitutional and Policy Implications

None

7.2 Environmental implications

Does your report have any	No ⊠	Yes □
environmental implications:		

7.3 Legal Implications

None

7.4 Staff Implications

Does your report impact on staff resources or result in any additional staffing resources being required?

No	
Yes	
` •	ease indicate whether or not it is part of the approved staffing whether the posts are budgeted for etc.)
7.5 Other Servi	ces Consulted
Solomzi Mdla	angaso & Siphelele Mehlo of Transport Department.
ANNEXURE E: REME GUIDELINE FOR FURTHER DETA	DIAL ENGINEERING MEASURES PROGRAMME SCREENING
NAME	Chrystal Frantz
CONTACT NUMBERS	021 444 7531
E-MAIL ADDRESS	Chrystal.Frantz@capetown.gov.za
DIRECTORATE	Urban Management
FILE REF NO	

Date _____

Comments

ANNEXURE E

REMEDIAL ENGINEERING MEASURES PROGRAMME SCREENING GUIDELINE

	IF ASSIST	TANCE IS REQUIRED TO COMPLETE THIS SCREENING GUIDELINE, PLEASE REQUEST FROM YOUR ICLL MANAGER THE NAME AND CONTACT DETAILS OF THE LOCAL TRANSPORT DEPARTMENT OF FICIAL	
	SUBURE	HELDENBENG ESTATE / HELENA HEIGHIS	
1	SUBCOL	incil 24	
1	WARD	F COUNCILLOR GREGORY. PECK.	
L	NAME C	F COUNCILLOR GREGORY. PECK.	
Γ	LOCATI	ON	
1	STREET NAME IRENE.		
		SECTION(S) BEND NHERE HEREWOOD JOINS INFINE	
	INTERS		
		(DESCRIBE EXACTLY WHERE YOU WISH TO SEE REMEDIAL ENGINEERING MEASURES IMPLEMENTED)	
	CLASS	OF ROAD 3.	
1			
	GUIDELINES		
	1.	IS THE STREET OR INTERSECTION USED BY PUBLIC TRANSPORT?(YES) NO	
	2.	ARE YOU AWARE OF ANY ACCIDENTS AT THE LOCATION IN THE PRECEDING	
		TWELVE MONTHS?YES (NO)	
	3.	DOES A HIGH VOLUME OF TRAFFIC USE THE ROAD?(.YES) NO	
ž,	4.	DOES A HIGH VOLUME OF "RAT RUN" TRAFFIC USE THE ROAD?(YES) NO	
	5.	IS A SURFACED SIDEWALK PROVIDED ALONG THE ROAD?YES (NO)	
	6.	ARE THERE MANY ACCESSES (DRIVEWAYS) ON THE ROAD?	
	7.	DO RESIDENTS OR OTHER DRIVERS PARK VEHICLES ON THE ROAD?	
	8.	DO MANY PEDESTRIANS OR CYCLISTS USE THE ROAD?(YES)NO	
	9.	DO ANY PUBLIC AMENITIES ABUT THE ROAD?YES NO	
	10.	ARE VEHICLE SPEEDS ACCEPTABLE OR UNACCEPTABLE?	
	11.	IF REMEDIAL ENGINEERING MEASURES ARE IMPLEMENTED, COULD THROUGH	
		TRAFFIC BE TRANSFERRED TO ANOTHER PARALLEL RESIDENTIAL STREET?YES NO	

OTHER COMMENTS
RECORD OTHER LOCAL INSIGHTS INTO TRAFFIC PATTERNS AND / OR DRIVER BEHAVIOUR THAT MIGHT ASSIST THE TRANSPORT DEPARTMENT IN ASSESSING THIS REQUEST
DrivERS SPEED DOWN THE HILL AND INTO THIS RIGHT HAND BEND
BEND DOWN" SIGNS AND SIGN
PUBLIC CONSULTATION
HAS THE PUBLIC BEEN CONSULTED ON THIS REQUEST TO DATE? YES NO IF YES, PLEASE EXPAND. A COMPUTANT FROM A RESIDENT LIVING ON THE BEND.
SKETCH AS THE DOLL OF THE DOLL
A SKETCH OF THE ROAD AND / OR PICTORIAL DESCRIPTION OF A PROBLEM
HARMOUD. ATHOL CRESCENT.
ARLINETON
FUNDING ()
IS FUNDING AVAILABLE FROM THE WARD ALLOCATION OR OTHER SOURCES OR IS FUNDING TO BE
SOUGHT ON THE DEPARTMENTAL CAPITAL BUDGET?
ND.
WARD COUNCILLOR'S ENDORSEMENT I HAVE VISITED THE AREA, SPOKEN TO THE APPLICANT AND RESIDENTS OF THE AFFECTED STREET,
AND AM SATISFIED THAT THE REQUEST IS JUSTIFIED / NOT JUSTIFIED. DO / DO NOT RECOMMEND
THAT THIS REQUEST FOR REMEDIAL ENGINEERING MEASURES BE TRANSMITTED TO THE TRANSPORT DEPARTMENT FOR TECHNICAL ASSESSMENT.
C O
15/8/2021
PRINT NAME SIGNATURE DATE
Screening Guideline Page 2 of 2
y² x ⊂